

ASHTON UNDER HILL

INTEGRATED TRANSPORT SERVICE RISK ASSESSMENT FORM

WORK PLACE: ASHTON UNDER HILL, WORCESTERSHIRE

ASSESSMENT BY: M ENGLISH

WORK ACTIVITY: MOBILE VA SIGN INSTALLATION

DESIGNATION:

DATE:

REVIEW DATE:

HAZARD	PEOPLE AT RISK	HARM	RISK RATING	PREVENTATIVE MEASURES	ADDITIONAL INFORMATION
Weather – raining, windy	Lengthsmen	Injury from working in adverse weather conditions	MEDIUM	<ul style="list-style-type: none"> ▪ Check weather forecast before setting out to work ▪ Do no work in heavy rain, snow, sleet, hail and/or strong winds 	<ul style="list-style-type: none"> • Lengthsmen to be provided with VAS rota list and location details • Lengthsmen to receive induction / tool box talk, regarding installation process and maintenance regime and provided with risk assessment. • Parish / Town Council to monitor effectiveness of VAS location sites • Keep First Aid box on site
Road traffic	Lengthsmen and members of the public	Injury from passing vehicles	MEDIUM/HIGH	<ul style="list-style-type: none"> ▪ VAS location assessment carried out using approved criteria. • Wear hi-visibility clothing 	
Work above ground level	Lengthsmen	Injury from falling off ladder	LOW	<ul style="list-style-type: none"> ▪ Use ladder which is in good repair, long enough to reach desired area of work easily, and tied off to prevent movement. ▪ Two man working 	

ASHTON UNDER HILL

Manual handling	Lengthsmen	Injury from lifting and lowering VA signs	LOW	<ul style="list-style-type: none">• Use correct manual handling techniques• Wear safety gloves & safety boots
------------------------	-------------------	--	------------	--